



DoD Web Site for MSDS

Army users can now view and print Material Safety Data Sheets (MSDS) on the Internet. The same info available on the quarterly Hazardous Materials Information System CD-ROMs is now available by clicking on:

<http://www.dliss.dla.mil/hmis/>

HMMWV Hot Starts

If you have a HMMWV that will not restart after the engine gets hot, eyeball the serial number of the fuel injection pump. Some pre-1994 GM 6.2L and 6.5L fuel injection pumps have had hot engine restart problems. Pumps with serial numbers under the break number shown below should be replaced by your support unit. Report all such pumps to support so they can replace them with a new fuel injection pump that has an improved hydraulic head and rotor assembly.

Pump part number	Serial Number Break
DB2829-4523	7539307
DB2829-4879	8064583
DB2831-5149	7768648
DB2831-5079	7768648

HMMWV Seatbelt MWO

The only way you can get 3-point seatbelts installed correctly in your HMMWV is by having your support apply MWO 9-2320-280-35-2. *You* cannot order all the parts needed from the supply system. Only your installation MWO coordinator can do that. If you have installed your own 3-point seatbelts, your vehicle is unsafe. Remove the belts and contact your MWO coordinator to have the seatbelts installed correctly. See TACOM Maintenance Advisory Message (MAM) 99-004 for the details. Note that the correct kit NSN for the front seats of non-armored HMMWVs is 2540-01-387-4018, not NSN 2540-01-387-5682.

SEE Hydraulic Filter

NSN 4330-01-273-2833 gets the small emplacement excavator's hydraulic filter that's shown as Item 20 in Fig 317 of TM 5-2420-224-24P. The NSN shown in the TM gets the wrong filter.

MLRS Charging

Page 39 in PS 570 (May 00) steered you wrong on charging the MLRS launcher/loader module (LLM) batteries. To charge the batteries, run the engine at 1,200 to 1,400 rpm with the interconnect switch—*not* the fire control panel—on.

Right Chains for M35A3 Tires

The tire chains in TM 9-2320-386-10's additional authorization list (AAL), NSN 2540-00-933-9022, will not fit the M35A3 2 1/2-ton truck. The right chains are PN S05SV, CAGE 4N506, available only from the vendor, PEWAG Austria GmbH. In Europe, call 43 316 6070, Ext 246, fax 43 316 6070 100, or e-mail:

Koe@pewag.com

In CONUS, call (800) 526-3924 or (630) 323-4342, fax (630) 323-2292 or e-mail:

peterb@pewagchain.com

Also, you need one pair only, for the intermediate axle. The AAL is wrong in requiring three pairs. The TM is scheduled to be changed.

POL User's Guide

Need info on the storage, use and disposal of Army petroleum, oils and lubricants (POL)? A booklet with that, plus a list of the hazardous or toxic components of POL and hotline numbers for info on state and local restrictions, is available from:

US Army TACOM-TARDEC
ATTN: AMSTA-TR-D1210
Warren, MI 48397-5000

Call DSN 786-4222 or (810) 574-4222. Or e-mail:

dash@tacom.army.mil

Mortar Repair Kits

Armorers, you should be getting your mortars back from support quicker, thanks to new parts kits. The kits contain all the parts that are replaced during semiannual maintenance. DS orders the M224 mortar kit with NSN 1015-01-452-1191, the M252 kit with NSN 1015-01-451-5789, and the M120/121 kit with NSN 1015-01-452-9634.

Vehicle Glass Sealer

NSN 8030-00-057-4109 gets a 5-oz tube of glass sealer. This clear, fast-drying liquid seals cracks and small openings in windows, windshields and taillights. Appendix A of CTA 50-970 is your ordering authority.

SEE Backup Alarm

NSN 6350-01-210-8149 gets the backup alarm for the small emplacement excavator. The NSN shown for Item 5 in Fig 77 of TM 5-2420-224-24P is no longer available.

SDU-5E Strobe Battery

The BA-1574 mercury battery, NSN 6135-00-073-8939, for your SDU-5E strobe light is no longer available, even though the FED LOG AMDF says it is. Power your strobe light instead with a BA-5374 lithium battery, NSN 6135-01-455-9646.

M1052A2 Chain Assembly

NSN 4010-01-447-0753 gets a chain assembly with hook for the 1 1/2-ton trailer. This assembly replaces Items 5, 6 and 7 in Fig 24 of TM 9-2330-213-14&P.

Send Us Your Stories!

Can you remember a time when PS Magazine "saved your bacon" with a timely article or by answering a maintenance-related question? If so, we want to hear related question? The best ones will be reprinted in our 50th anniversary issue next June. Send your story to:

PS Magazine
ATTN: AMXLS-LP, Bldg 5307
Redstone Arsenal, AL 35898-7466

Or e-mail it to:

psmag@logsa.army.mil

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life *right now* on the Condition of Your Equipment?